



Model: DRIFT

- Useful for removing taper shank drills from all taper shank drill presses, radial arm drills and mill drills
- By using the Bramley Hammer Drill Drift you only need two hands – one for the spring loaded drift & one to catch the drill
- Very easy operation.... Tap, tap and the drill is safely out
- Traditional method requires 3 hands, one for the hammer, one for the drift and the third to catch the drill otherwise the drill falls out and damages the table or the drill
- Can double as a “soft” hammer

Scan for Drift Video

